

From: "Davis, Mike" <MDavis@archcoal.com>
To: "Carter Reed" <creed@fs.fed.us>, "Chris Hansen (E-mail)" <CHansen@archcoal.com>, "Craig Hilton (E-mail)" <CHilton@archcoal.com>, "Dana Dean" <danadean@utah.gov>, "Daron Haddock (E-mail)" <daronhaddock@utah.gov>, "Dave Darby (E-mail)" <davedarby@utah.gov>, "Erik Petersen (E-mail)" <petersen@relia.net>, "Jerriann Ernstsens (E-mail)" <jerriannernstsens@utah.gov>, "Ken May (E-mail)" <KMay@archcoal.com>, "Mark Bunnell (E-mail)" <MBunnell@archcoal.com>, "Pam Grubaugh-Littig (E-mail)" <Pamgrubaughlittig@utah.gov>, "Pete Hess (E-mail)" <petehess@utah.gov>, "Stan Perkes" <sperkes@blm.gov>, "Steve Fluke (E-mail)" <stevefluke@utah.gov>, "Susan White (E-mail)" <susanwhite@utah.gov>, "Tom Lloyd" <twlloyd@fs.fed.us>
Date: 01/14/2004 7:27:15 AM
Subject: East Fork Box Canyon Monitoring 1/5/04

The mine tried to make it up to the East Fork on January 5, 2004 but the snow on the road in Link Canyon was still too deep and it became too unreasonable to proceed.

A conference call on January 7, 2004 was made to discuss the monitoring schedule for East Fork Box Canyon due to the winter weather conditions with Daron Haddock and Steve Fluke of the Division and Tom Lloyd of the Forest Service. It was decided to try and make another combined trip on January 14, 2004 on snowmobiles to evaluate the situation and to conclude if the monitoring schedule needs to be modified due to the winter weather conditions and safety of hiking down into the canyon under these conditions.

The updated face location map is attached.

Mike

<<3LPE WEEKLY MONITORING PDF 01-12-04.pdf>>

